



**Hunter 440200SP reparatieset t.b.v.
MINI - CLIK regensensor**

NexaParts B.V.
Duurzaamheidstraat 33
8094SC, Hattemerbroek

E-MAIL info@nexaparts.nl
TEL +31 38 2024038
KVK 87151227

Hunter 440200SP repair kit T.b.v Mini-Click

<https://www.nexaparts.com/hunter-440200sp-repair-kit-t.b.v-mini-click>

Specificaties

Productnummer	H1.60.370
EAN	8720026089101
Merk	Hunter
Categorie	Irrigation
Style	Hunter 440200SP reparatieset t.b.v MINI-CLIK
model	Onderdelen
Model	440200SP reparatieset t.b.v MINI-CLIK

